

1a) Arizona Department of Environmental
Quality

Compliance Status Reports-Water

Arizona Department of Environmental Quality
 Drinking Water Monitoring and Protection Unit
 Mail Code 5415B-2
 1110 West Washington Street
 Phoenix, AZ 85007

Drinking Water Compliance Status Report

System Name EPCOR WATER - LAKE HAVASU	System Type <input checked="" type="checkbox"/> Community	Is system consecutive? <input type="checkbox"/> Yes, to PWS #
System ID # 08015	<input type="checkbox"/> Non-transient Non-community <input type="checkbox"/> Transient Non-community	
		<input checked="" type="checkbox"/> No

Overall compliance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Monitoring and Reporting status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Comments: The PWS has arsenic treatment on EPDS002 and is on quarterly monitoring for the life of the treatment plant.		

Operation and Maintenance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Date of last Sanitary Survey	6/28/16	Inspector
		Mario Casillas, ADEQ Phoenix
Major unresolved/ongoing operation and maintenance deficiencies:		
<input type="checkbox"/> unable to maintain 20psi	<input type="checkbox"/> inadequate storage	
<input type="checkbox"/> cross connection/backflow problems	<input type="checkbox"/> surface water treatment rule	
<input type="checkbox"/> treatment deficiencies	<input type="checkbox"/> ATC/AOC	
<input type="checkbox"/> certified operator	<input type="checkbox"/> other =	
Comments: During the last sanitary survey, recommendation was made for finished water storage (the tank at the Pero yard needs to be serviced).		

Is an ADEQ administrative order in effect?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Comments: None		

System Information			
Population Served	4068		
Service Connections	1627		
Number of Entry Points to the Distribution System	2		
Number of Sources	3		
Initial Monitoring Year	1993		
Monitoring Assistance Program (MAP) System	<input checked="" type="checkbox"/>	Yes	<input type="checkbox"/> No

Evaluation completed by	Donna Calderon, Senior Drinking Water Technical Program Specialist Drinking Water Monitoring and Protection Unit		
Phone	602-771-4641	Date	March 1, 2017
<input checked="" type="checkbox"/>	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and PWS is in compliance.		
<input type="checkbox"/>	Based upon the monitoring and reporting deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.		
<input type="checkbox"/>	Based upon the operation and maintenance deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.		

This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.

Arizona Department of Environmental Quality
Drinking Water Monitoring and Protection Unit
 Mail Code 5415B-2
 1110 West Washington Street
 Phoenix, AZ 85007

Drinking Water Compliance Status Report

System Name	System Type	Is system consecutive?
EPCOR WATER - MOHAVE	<input checked="" type="checkbox"/> Community	<input type="checkbox"/> Yes, to PWS #
System ID #	<input type="checkbox"/> Non-transient Non-community	
08032	<input type="checkbox"/> Transient Non-community	<input checked="" type="checkbox"/> No

Overall compliance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Monitoring and Reporting status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Comments: None		

Operation and Maintenance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Date of last Sanitary Survey	11-19-14	Inspector
		Deborah Schadewald-Kohler, PHX
Major unresolved/ongoing operation and maintenance deficiencies:		
<input type="checkbox"/> unable to maintain 20psi	<input type="checkbox"/> inadequate storage	
<input type="checkbox"/> cross connection/backflow problems	<input type="checkbox"/> surface water treatment rule	
<input type="checkbox"/> treatment deficiencies	<input type="checkbox"/> atc/aoc	
<input type="checkbox"/> certified operator	<input type="checkbox"/> other =	
Comments: None		

Is an ADEQ administrative order in effect?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Comments: None		

System Information	
Population Served	36330
Service Connections	14532
Number of Entry Points to the Distribution System	8
Number of Sources	9
Initial Monitoring Year	1994
Monitoring Assistance Program (MAP) System	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

Evaluation completed by	Donna Calderon, Senior Drinking Water Technical Program Specialist Drinking Water Monitoring and Protection Unit		
Phone	602-771-4641	Date	March 1, 2017
<input checked="" type="checkbox"/>	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		
<input type="checkbox"/>	Based upon the monitoring and reporting deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		
<input type="checkbox"/>	Based upon the operation and maintenance deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		

This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.

Arizona Department of Environmental Quality
 Drinking Water Monitoring and Protection Unit
 Mail Code 5415B-2
 1110 West Washington Street
 Phoenix, AZ 85007

Drinking Water Compliance Status Report

System Name	System Type	Is system consecutive?
EPCOR WATER - CAMP MOHAVE	<input checked="" type="checkbox"/> Community	<input checked="" type="checkbox"/> Yes, to PWS # 08063 on an emergency basis
System ID #	<input type="checkbox"/> Non-transient Non-community	
08037	<input type="checkbox"/> Transient Non-community	<input type="checkbox"/> No

Overall compliance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Monitoring and Reporting status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Comments: None		

Operation and Maintenance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Date of last Sanitary Survey	11-19-14	Inspector
		Deborah Schadewald-Kohler, PHX
Major unresolved/ongoing operation and maintenance deficiencies:		
<input type="checkbox"/> unable to maintain 20psi	<input type="checkbox"/> inadequate storage	
<input type="checkbox"/> cross connection/backflow problems	<input type="checkbox"/> surface water treatment rule	
<input type="checkbox"/> treatment deficiencies	<input type="checkbox"/> ATC/AOC	
<input type="checkbox"/> certified operator	<input type="checkbox"/> other =	
Comments: None		

Is an ADEQ administrative order in effect?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Comments: None		

System Information	
Population Served	193
Service Connections	78
Number of Entry Points to the Distribution System	1
Number of Sources	1
Initial Monitoring Year	1994
Monitoring Assistance Program (MAP) System	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

Evaluation completed by	Donna Calderon, Senior Drinking Water Technical Program Specialist Drinking Water Monitoring and Protection Unit		
Phone	602-771-4641	Date	March 1, 2017
<input checked="" type="checkbox"/>	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and PWS is in compliance.		
<input type="checkbox"/>	Based upon the monitoring and reporting deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.		
<input type="checkbox"/>	Based upon the operation and maintenance deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.		

This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.

Arizona Department of Environmental Quality
 Drinking Water Monitoring and Protection Unit
 Mail Code 5415B-2
 1110 West Washington Street
 Phoenix, AZ 85007

Drinking Water Compliance Status Report

System Name	System Type	Is system consecutive?
EPCOR WATER - LAKE MOHAVE HIGHLANDS	<input checked="" type="checkbox"/> Community	<input checked="" type="checkbox"/> Yes, to PWS # 08068 on an emergency basis.
System ID #	<input type="checkbox"/> Non-transient Non-community	
08062	<input type="checkbox"/> Transient Non-community	<input type="checkbox"/> No

Overall compliance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Monitoring and Reporting status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Comments: None		

Operation and Maintenance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Date of last Sanitary Survey	11-19-14	Inspector
		Deborah Schadewald-Kohler, PHX
Major unresolved/ongoing operation and maintenance deficiencies:		
<input type="checkbox"/> unable to maintain 20psi	<input type="checkbox"/> inadequate storage	
<input type="checkbox"/> cross connection/backflow problems	<input type="checkbox"/> surface water treatment rule	
<input type="checkbox"/> treatment deficiencies	<input type="checkbox"/> ATC/AOC	
<input type="checkbox"/> certified operator	<input type="checkbox"/> other =	
Comments: None		

Is an ADEQ administrative order in effect?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Comments: None		

System Information	
Population Served	675
Service Connections	270
Number of Entry Points to the Distribution System	1
Number of Sources	2
Initial Monitoring Year	1994
Monitoring Assistance Program (MAP) System	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

Evaluation completed by	Donna Calderon, Senior Drinking Water Technical Program Specialist Drinking Water Monitoring and Protection Unit		
Phone	602-771-4641	Date	March 1, 2017
<input checked="" type="checkbox"/>	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and PWS is in compliance.		
<input type="checkbox"/>	Based upon the monitoring and reporting deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.		
<input type="checkbox"/>	Based upon the operation and maintenance deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.		

This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.

Arizona Department of Environmental Quality
 Drinking Water Monitoring and Protection Unit
 Mail Code 5415B-2
 1110 West Washington Street
 Phoenix, AZ 85007

Drinking Water Compliance Status Report


System Name	System Type	Is system consecutive?
EPCOR WATER - DESERT FOOTHILLS	<input checked="" type="checkbox"/> Community	<input type="checkbox"/> Yes, to PWS #
System ID #	<input type="checkbox"/> Non-transient Non-community	<input checked="" type="checkbox"/> No
08137	<input type="checkbox"/> Transient Non-community	

Overall compliance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Monitoring and Reporting status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Comments: None		

Operation and Maintenance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Date of last Sanitary Survey	11-19-14	Inspector
		Deborah Schadewald-Kohler, PHX
Major unresolved/ongoing operation and maintenance deficiencies:		
<input type="checkbox"/> unable to maintain 20psi	<input type="checkbox"/> inadequate storage	
<input type="checkbox"/> cross connection/backflow problems	<input type="checkbox"/> surface water treatment rule	
<input type="checkbox"/> treatment deficiencies	<input type="checkbox"/> ATC/AOC	
<input type="checkbox"/> certified operator	<input type="checkbox"/> other =	
Comments: None		

Is an ADEQ administrative order in effect?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Comments: None		

System Information	
Population Served	2860
Service Connections	1116
Number of Entry Points to the Distribution System	2
Number of Sources	2
Initial Monitoring Year	1998
Monitoring Assistance Program (MAP) System	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

Evaluation completed by	Donna Calderon, Senior Drinking Water Technical Program Specialist Drinking Water Monitoring and Protection Unit 		
Phone	602-771-4641	Date	March 1, 2017
<input checked="" type="checkbox"/>	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and PWS is in compliance.		
<input type="checkbox"/>	Based upon the monitoring and reporting deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.		
<input type="checkbox"/>	Based upon the operation and maintenance deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.		

This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.

Arizona Department of Environmental Quality
Drinking Water Monitoring and Protection Unit
 Mail Code 5415B-2
 1110 West Washington Street
 Phoenix, AZ 85007

Drinking Water Compliance Status Report

System Name	System Type	Is system consecutive?
EPCOR WATER - ARIZONA GATEWAY	<input type="checkbox"/> Community	<input type="checkbox"/> Yes, to PWS #
System ID #	<input checked="" type="checkbox"/> Non-transient Non-community	
08163	<input type="checkbox"/> Transient Non-community	<input checked="" type="checkbox"/> No

Overall compliance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Monitoring and Reporting status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies

Comments: The PWS changed system type from Transient Non-community to Non-transient Non-community on May 1, 2016. As a result, the PWS is now in the Monitoring Assistance Program (MAP). MAP will conduct the initial monitoring for IOCs, SOCs, VOCs, and asbestos beginning in 2017. The PWS will begin initials for lead and copper starting in 2017. Nitrate and nitrite remain on the existing sampling schedules and will be sampled by MAP beginning in 2017.

Operation and Maintenance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Date of last Sanitary Survey	4-18-12	Inspector
		Deborah Schadewald-Kohler, PHX

Major unresolved/ongoing operation and maintenance deficiencies:

<input type="checkbox"/> unable to maintain 20psi	<input type="checkbox"/> inadequate storage
<input type="checkbox"/> cross connection/backflow problems	<input type="checkbox"/> surface water treatment rule
<input type="checkbox"/> treatment deficiencies	<input type="checkbox"/> ATC/AOC
<input type="checkbox"/> certified operator	<input type="checkbox"/> other =

Comments: None

Is an ADEQ administrative order in effect?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Comments: None		

System Information	
Population Served	2215
Service Connections	4
Number of Entry Points to the Distribution System	1
Number of Sources	2
Initial Monitoring Year	2003
Monitoring Assistance Program (MAP) System	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

Evaluation completed by	Donna Calderon, Senior Drinking Water Technical Program Specialist Drinking Water Monitoring and Protection Unit		
Phone	602-771-4641	Date	March 1, 2017

<input checked="" type="checkbox"/>	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and PWS is in compliance.
<input type="checkbox"/>	Based upon the monitoring and reporting deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.
<input type="checkbox"/>	Based upon the operation and maintenance deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.

This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.

Arizona Department of Environmental Quality
Drinking Water Monitoring and Protection Unit
 Mail Code 5415B-2
 1110 West Washington Street
 Phoenix, AZ 85007

Drinking Water Compliance Status Report

System Name	System Type	Is system consecutive?
EPCOR WATER - RIO VISTA RANCHES	<input checked="" type="checkbox"/> Community	<input checked="" type="checkbox"/> Yes, to PWS # 08063
System ID #	<input type="checkbox"/> Non-transient Non-community	
08333	<input type="checkbox"/> Transient Non-community	<input type="checkbox"/> No

Overall compliance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Monitoring and Reporting status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Comments: None		

Operation and Maintenance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Date of last Sanitary Survey	3-29-16	Inspector
		Mario Casillas, ADEQ Phoenix
Major unresolved/ongoing operation and maintenance deficiencies:		
<input type="checkbox"/> unable to maintain 20psi	<input type="checkbox"/> inadequate storage	
<input type="checkbox"/> cross connection/backflow problems	<input type="checkbox"/> surface water treatment rule	
<input type="checkbox"/> treatment deficiencies	<input type="checkbox"/> ATC/AOC	
<input type="checkbox"/> certified operator	<input type="checkbox"/> other =	
Comments: None		

Is an ADEQ administrative order in effect?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Comments: None		

System Information	
Population Served	59
Service Connections	25
Number of Entry Points to the Distribution System	consecutive
Number of Sources	consecutive
Initial Monitoring Year	1997
Monitoring Assistance Program (MAP) System	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

Evaluation completed by	Donna Calderon, Senior Drinking Water Technical Program Specialist Drinking Water Monitoring and Protection Unit		
Phone	602-771-4641	Date	March 1, 2017
<input checked="" type="checkbox"/>	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and PWS is in compliance.		
<input type="checkbox"/>	Based upon the monitoring and reporting deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.		
<input type="checkbox"/>	Based upon the operation and maintenance deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.		

This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.

Arizona Department of Environmental Quality
Drinking Water Monitoring and Protection Unit
 Mail Code 5415B-2
 1110 West Washington Street
 Phoenix, AZ 85007

Drinking Water Compliance Status Report

System Name	System Type	Is system consecutive?
EPCOR WATER - NORTH MOHAVE VALLEY	<input checked="" type="checkbox"/> Community	<input type="checkbox"/> Yes, to PWS #
System ID #	<input type="checkbox"/> Non-transient Non-community	
08068	<input type="checkbox"/> Transient Non-community	<input checked="" type="checkbox"/> No

Overall compliance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Monitoring and Reporting status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Comments: None		

Operation and Maintenance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Date of last Sanitary Survey	10-28-13	Inspector
		Matthew Ritter, PHX
Major unresolved/ongoing operation and maintenance deficiencies:		
<input type="checkbox"/> unable to maintain 20psi	<input type="checkbox"/> inadequate storage	
<input type="checkbox"/> cross connection/backflow problems	<input type="checkbox"/> surface water treatment rule	
<input type="checkbox"/> treatment deficiencies	<input type="checkbox"/> atc/aoc	
<input type="checkbox"/> certified operator	<input type="checkbox"/> other =	
Comments: None		

Is an ADEQ administrative order in effect?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Comments: None		

System Information	
Population Served	4886
Service Connections	2019
Number of Entry Points to the Distribution System	4
Number of Sources	7
Initial Monitoring Year	1994
Monitoring Assistance Program (MAP) System	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

Evaluation completed by	Donna Calderon, Senior Drinking Water Technical Program Specialist Drinking Water Monitoring and Protection Unit		
Phone	602-771-4641	Date	March 1, 2017
<input checked="" type="checkbox"/>	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		
<input type="checkbox"/>	Based upon the monitoring and reporting deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		
<input type="checkbox"/>	Based upon the operation and maintenance deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		

This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.

Arizona Department of Environmental Quality
Drinking Water Monitoring and Protection Unit
 Mail Code 5415B-2
 1110 West Washington Street
 Phoenix, AZ 85007

Drinking Water Compliance Status Report

System Name EPCOR WATER - TUBAC	System Type <input checked="" type="checkbox"/> Community	Is system consecutive? <input type="checkbox"/> Yes, to PWS #
System ID # 12001	<input type="checkbox"/> Non-transient Non-community	<input checked="" type="checkbox"/> No
	<input type="checkbox"/> Transient Non-community	

Overall compliance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Monitoring and Reporting status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Comments: The PWS has arsenic treatment on EPDS005 and is on quarterly monitoring for the life of the treatment plant.		

Operation and Maintenance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Date of last Sanitary Survey	6-21-16	Inspector
		Nam Ho, ADEQ SRO
Major unresolved/ongoing operation and maintenance deficiencies:		
<input type="checkbox"/> unable to maintain 20psi	<input type="checkbox"/> inadequate storage	
<input type="checkbox"/> cross connection/backflow problems	<input type="checkbox"/> surface water treatment rule	
<input type="checkbox"/> treatment deficiencies	<input type="checkbox"/> atc/aoc	
<input type="checkbox"/> certified operator	<input type="checkbox"/> other =	
Comments: Minor deficiency assigned to finished water storage (install an overflow pipe on storage tank). NOC closed 8-19-2016.		

Is an ADEQ administrative order in effect?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Comments: None		

System Information			
Population Served	1485		
Service Connections	594		
Number of Entry Points to the Distribution System	2		
Number of Sources	3		
Initial Monitoring Year	1993		
Monitoring Assistance Program (MAP) System	<input checked="" type="checkbox"/>	Yes	<input type="checkbox"/> No

Evaluation completed by	Donna Calderon, Senior Drinking Water Technical Program Specialist Drinking Water Monitoring and Protection Unit		
Phone	602-771-4641	Date	March 1, 2017
<input checked="" type="checkbox"/>	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		
<input type="checkbox"/>	Based upon the monitoring and reporting deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		
<input type="checkbox"/>	Based upon the operation and maintenance deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		

This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.

Arizona Department of Environmental Quality
Drinking Water Monitoring and Protection Unit
 Mail Code 5415B-2
 1110 West Washington Street
 Phoenix, AZ 85007

Drinking Water Compliance Status Report

System Name EPCOR WATER -WILLOW VALLEY/ LAKE CIMARRON	System Type <input checked="" type="checkbox"/> Community	Is system consecutive? <input type="checkbox"/> Yes, to PWS #
System ID # 08129	<input type="checkbox"/> Non-transient Non-community <input type="checkbox"/> Transient Non-community	<input checked="" type="checkbox"/> No

Overall compliance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Monitoring and Reporting status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Comments: While not required to meet water quality standards, the PWS has a treatment for the removal of iron and manganese to address aesthetics. The PWS also uses chlorine dioxide for disinfection / treatment.		

Operation and Maintenance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Date of last Sanitary Survey	3-30-16	Inspector
		Mario Casillas, ADEQ Phoenix
Major unresolved/ongoing operation and maintenance deficiencies:		
<input type="checkbox"/> unable to maintain 20psi	<input type="checkbox"/> inadequate storage	
<input type="checkbox"/> cross connection/backflow problems	<input type="checkbox"/> surface water treatment rule	
<input type="checkbox"/> treatment deficiencies	<input type="checkbox"/> atc/aoc	
<input type="checkbox"/> certified operator	<input type="checkbox"/> other =	
Comments: None		

Is an ADEQ administrative order in effect?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Comments: None		

System Information			
Population Served	367		
Service Connections	131		
Number of Entry Points to the Distribution System	1		
Number of Sources	2		
Initial Monitoring Year	1995		
Monitoring Assistance Program (MAP) System	<input checked="" type="checkbox"/>	Yes	<input type="checkbox"/> No

Evaluation completed by	Donna Calderon, Senior Drinking Water Technical Program Specialist Drinking Water Monitoring and Protection Unit		
Phone	602-771-4641	Date	March 1, 2017
<input checked="" type="checkbox"/>	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		
<input type="checkbox"/>	Based upon the monitoring and reporting deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		
<input type="checkbox"/>	Based upon the operation and maintenance deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		

This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.

Arizona Department of Environmental Quality
Drinking Water Monitoring and Protection Unit
 Mail Code 5415B-2
 1110 West Washington Street
 Phoenix, AZ 85007

Drinking Water Compliance Status Report

System Name	System Type	Is system consecutive?
EPCOR WATER - WILLOW VALLEY / KING STREET	<input checked="" type="checkbox"/> Community	<input type="checkbox"/> Yes, to PWS #
System ID #	<input type="checkbox"/> Non-transient Non-community	<input checked="" type="checkbox"/> No
08040	<input type="checkbox"/> Transient Non-community	

Overall compliance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Monitoring and Reporting status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Comments: While not required to meet water quality standards, the PWS has treatment for the removal of iron and manganese to address aesthetics. The PWS also uses chlorine dioxide for disinfection / treatment.		

Operation and Maintenance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Date of last Sanitary Survey	3-30-16	Inspector
		Mario Casillas, ADEQ Phoenix
Major unresolved/ongoing operation and maintenance deficiencies:		
<input type="checkbox"/> unable to maintain 20psi	<input type="checkbox"/> inadequate storage	
<input type="checkbox"/> cross connection/backflow problems	<input type="checkbox"/> surface water treatment rule	
<input type="checkbox"/> treatment deficiencies	<input type="checkbox"/> ATC/AOC	
<input type="checkbox"/> certified operator	<input type="checkbox"/> other =	
Comments: None		

Is an ADEQ administrative order in effect?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Comments: None		

System Information	
Population Served	2886
Service Connections	1031
Number of Entry Points to the Distribution System	1
Number of Sources	2
Initial Monitoring Year	1994
Monitoring Assistance Program (MAP) System	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

Evaluation completed by	Donna Calderon, Senior Drinking Water Technical Program Specialist Drinking Water Monitoring and Protection Unit		
Phone	602-771-4641	Date	March 1, 2017
<input checked="" type="checkbox"/>	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and PWS is in compliance.		
<input type="checkbox"/>	Based upon the monitoring and reporting deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.		
<input type="checkbox"/>	Based upon the operation and maintenance deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4, and/or PWS is not in compliance.		

This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.